



ESTATOR DEL ALTERNADOR SIN REVESTIMIENTO DE 2 CABLES '84 '90 XL

Número de parte: DS195093

OEM: 2996784A

1988-1990	Harley-Davidson	Sportster 1200 XLH
1987-1990	Harley-Davidson	883 Hugger XLH
1986-1990	Harley-Davidson	Sportster 883 XLH
1986-1990	Harley-Davidson	883 Deluxe XLH
1986-1987	Harley-Davidson	Sportster 1100 XLH
1984-1985	Harley-Davidson	Roadster 1000 XLS
1984-1985	Harley-Davidson	Sportster 1000 XLX
1984-1985	Harley-Davidson	Sportster 1000 XLH
1984	Harley-Davidson	Sportster 1000 XR